

Date: Thursday, 21/06/2007 9:57:52 AM
User: Linda Locelle

Process Sheet

Spl 7

Customer : CC-DAR01 Dart Aerospace Ltd.	Drawing Name : D2844-1/-3
Job Number : 33029 <i>2</i>	
Estimate Number : 10804	
P.O. Number : <i>N/A</i>	Part Number : D28441
This Issue : 21/06/2007 S.O. No. : <i>N/A</i>	Drawing Number : REWORK
Prsht Rev. : NC	Project Number : <i>N/A</i>
First Issue : <i>N/A</i> Type : R&D GENERAL	Drawing Revision : <i>N/A</i>
Previous Run : 00015	Material : <i>N/A</i>
Written By : _____	Due Date : 28/06/2007
Checked & Approved By : _____	Qty: <i>52</i> Um: Each
Comment : _____	

Additional Product

Job Number



Seq. #: Machine Or Operation: Description :

1.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

REMOVE FROM STK:

D2844-1 B *B 3 2284* (4)*FF 07-06-21*D2844-3 B *B 29786* (2)*SB 07/06/21*

2.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

REWORK PER NCR 172

PER DRWG D2844 REV.A

FF 07-06-21

3.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

07-06-21 4/2

4.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

ID & STK

USING SAME BV/N

Flc/21 59

Date: Thursday, 21/06/2007 9:57:52 AM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D2844-1/-3

Job Number: 33029

Part Number: D28441

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Handwritten signature and date: 21/06/07

Job Completion

